

REENTRY PROCEDURE

WELL NAME: UPRR-Wells 01 DATE: 2/4/2016
 LOCATION: Qtr/Qtr: SWSW Section: 31 Township: 6N Range: 62W
 COUNTY: WELD STATE: CO API #: 05-123-07136

ENGINEER: Hunter Dunham 7 Day Notice Sent:
 (Please notify Engineer of any major changes prior to work) Do not start operations until:
 Notice Expires:

OBJECTIVE: Re-enter and re-plug

WELL DATA: Surface Csg: 8 5/8" 24# 143' KB Elevation: 4897'
 Surface Cmt: 130sxs to surface GL Elevation: 4886'
 Long St Csg: 7 7/8" open hole to 7206 (TD) TD: 7206'
 Long St Cmt: None PBTD:
 Long St Date: 2/19/1970
 Plug Info (1) 15sxs cement 120'/170'
 Plug Info (2) 10 sxs cement at surface
 Plug Info (3)
 Plug Info (4)
 Tubing: Rods:
 Pump:
 Misc.: Base Fox Hills 362', Deepest water well 196'

WELL STATUS: Well Abandoned 02/19/1970

COMMENTS: Plugging report notes that well is filled with heavy mud with cement plug 1/2 in and 1/2 out at surface casing shoe. No other plugging notes

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
- 7) NU flange adaptor and 5k BOP, test BOP.
- 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing, roll hole clean. Verify top of next cement plug inside of surface casing by tagging (TOC @ 120ft).
- 10) If unable to verify isolation of surface casing with tag of cement plug, set RBP inside surface casing
- 11) Once isolation of surface casing is established, either with tagging of surface plug or setting of RBP, pressure test surface casing to 200psi
- 12) After pressure test of surface casing, retrieve RBP or continue drill out of cement plug under surface casing shoe.
- 13) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
- 14) Continue RIH, cleaning out with drilling mud or water to 4000'
- 15) Circulate 2x hole volume (500bbl) to condition hole
- 16) TOO H with cone bit, drill collars, and 2 7/8" tubing.
- 17) PU and RIH with mule shoe and 2 7/8" tubing to 4000'.
- 18) RU cement crew and pump a balanced plug of 95sk 15.8 ppg Class G "neat" cement
 *95sxs assumes 25% excess volume needed
- 19) POOH to 475ft (100ft deeper than deepest water well)
- 20) RU cement crew and pump 200 sxs of 15.8ppg Class G "neat" cement bring cement to surface
 *200sxs assumes 25% excess volume needed
- 21) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC. If cement has fallen, top off back to surface
- 22) Let cement set over night, verify cement has not settled and is still at surface. RDMO