

WORKOVER PROCEDURE

WELL NAME:	OTTOSON 12-14G6		DATE:	3/14/2016	
LOCATION:					
Qtr/Qtr:	SE/SW	Section:	12	Township:	6N
Footages:	665	FSL	&	1994	FWL
COUNTY:	WELD		STATE:	CO	
			API #:	05-123-18233	
ENGINEER:	JOHNN HATCH		7 Day Notice Sent:		
	(Please notify Engineer of any major changes prior to work)		Do not start operations until:		
			Notice Expires:		
OBJECTIVE:	P&A				
WELL DATA:					
Surface Csg:	7" 17.0#, H-40 @ 470'			KB Elevation:	4787'
Surface Cmt:	325 sx			GL Elevation:	4773'
Long St Csg:	3 1/2" 7.70#, B-70 @ 7177.6'			TD:	7521'
Long St Cmt:	113 sx			PBTD:	7214'
Long St Date:	5/2/1994				
Plug Back (Sand or CIBP):					
Perforation Interval (1):	Niobrara Perforations 6900' - 7020'				
Perforation Interval (2):	Codell Perforations 7183' - 7194'				
Perforation Interval (3):					
Tubing:	2 1/16" 3.25", J-55 @ 7172.4'			Rods:	
Pump:					
Misc.:					
PRODUCTION STATUS:					
COMMENTS:					

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6850', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 520'. Pump 226 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.