

WORKOVER PROCEDURE

WELL NAME: MOORE 01 **DATE:** 3/15/2016
LOCATION:
Qtr/Qtr: NE/NE Section: 13 Township: 6N Range: 66W
Footages: 660 FNL & 660 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-12379
ENGINEER: JOHNN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 310' KB Elevation: 4790'
Surface Cmt: 250 sx GL Elevation: 4778'
Long St Csg: 4 1/2", 11.60#, J-55 @ 7272' TD: 7280'
Long St Cmt: 200 sx PBDT: 7226'
Long St Date: 4/10/1985

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7182' - 7199'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70#, J-55 @7170' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
 - 2) POOH w/ 2 3/8" tbg and lay down.
 - 3) RU WL. RIH w/ CIBP. Set CIBP @ 7132', pump 36 sx of cement on top.
 - 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
 - 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
 - 6) POOH w/ workstring to 420'. Pump 161 sx shoe plug. Cement to surface.
 - 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
 - 8) Cut surface casing off 6'-8' below ground.
 - 9) Clean up location. RDMOL.