

## WORKOVER PROCEDURE

**WELL NAME:** Rohr 15-06 **DATE:** 3/22/2016  
**LOCATION:**  
Qtr/Qtr: SE/NW Section: 15 Township: 4N Range: 64W  
Footages: 1976' FNL & 1794' FWL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-17604

**ENGINEER:** Jonathan Pomerantz (Noble) 303-228-4198 7 Day Notice Sent:  
B. Lawrence (Halliburton) 303.513.1199 Do not start operations until:  
(Please notify Engineer of any major changes prior to work) Notice Expires:

**OBJECTIVE:** Well Abandonment

**WELL DATA:** Surface Csg: 8-5/8"; 23 ppf; M-50 set at 512' KB Elevation: 4656'  
Surface Cmt: 261 sx GL Elevation: 4645'  
Long St Csg: 3-1/2"; 7.7 ppf; M-75 set at 6924' TD: 6940'  
Long St Cmt: 351 sx PBTD: 6887'  
Long St Date: 11/19/1993

Plug Back (Sand or CIBP):

Perforation Interval (1): Niobrara Perforations 6532' - 6682'  
Perforation Interval (2): Codell Perforations 6801' - 6812'  
Perforation Interval (3):  
Perforation Interval (4):  
Tubing: 2-1/16"; 3.25 ppf; J-55 @ 6792' Rods: NA  
Pump: NA  
Misc.: **Discrepancy with TD; drilling report and OH log = 6940'; ST RPT @ 6935'**

**PRODUCTION STATUS:**  
**COMMENTS:** No producing Sussex within 1 mile.

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6482', dump bail 2 sx of cement on top.
- 4) Perforate at 2500' and 612'.
- 5) Set CICR at 2400'.
- 6) RIH w/ CT and sting into CICR. Pump 90 sx cement below retainer, leaving 100' (5 sx) on top of CICR.
- 7) POOH and RD CT. Pump 235 sx (205 sx out & 30 sx in) shoe plug down production csg. Bring cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.