

WORKOVER PROCEDURE

WELL NAME: Monfort E #30-16 **DATE:** 4/1/2016

LOCATION: Qtr/Qtr: NE/SE Section: 30 Township: 6N Range: 65W

Footages: 1950' FSL & 720' FEL FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-23553

ENGINEER: John Hatch (Noble) 720.587.2377 7 Day Notice Sent: _____
B. Lawrence (Halliburton) 303.513.1199 Do not start operations until: _____
(Please notify Engineer of any major changes prior to work) Notice Expires: _____

OBJECTIVE: Well Abandonment

WELL DATA: Surface Csg: 8-5/8"; 24 ppf; J-55; set at 453' KB Elevation: 4724'
Surface Cmt: 340 sx GL Elevation: 4708'
Long St Csg: 4-1/2"; 11.6 ppf; M-80; set at 7473' TD: 7506'
Long St Cmt: 830 sx PBDT: 7450'
Long St Date: 2/8/2006

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7329' - 7346'
Perforation Interval (2): _____
Tubing: 2-3/8"; 4.7 ppf; J-55 @ 7317' Rods: NA
Pump: NA
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: No producing Sussex within 1 mile.

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7279'.
- 4) Perforate at 553'
- 5) RIH w/ CT and pump 30 sx on top of CIBP at 7279' then pump a 20 sx courtesy plug from 2500' to 2300'.
- 6) POOH and RD CT. Pump 215 sx (170 sx out & 45 sx in) shoe plug down production casing. Bring cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.