

WORKOVER PROCEDURE

WELL NAME: Bickling #3-43 **DATE:** 4/4/2016

LOCATION: Qtr/Qtr: SWSE Section: 3 Township: 6N Range: 65W

Footages: 670 FSL & 1984 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-21622

ENGINEER: John Hatch (Noble - 720-587-2377) 7 Day Notice Sent:
Tanner Boyd (Halliburton - 432-803-6064) Do not start operations until:
(Please notify Engineer of any major changes prior to work) Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8.625" 24# SET AT 396' KB Elevation: 4814
Surface Cmt: 280 sx GL Elevation: 4804
Long St Csg: 4.5" 11.6# SET AT 7245' TD: 7250
Long St Cmt: 220 sx PBTD: 7229
Long St Date: 11/30/2003

Plug Back (Sand or CIBP):
Perforation Interval (1): CODELL Perforations 7128' - 7141'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 2.375" 4.7# @ 7122' Rods: NA
Pump: NA
Misc.: **SPUD DATE: 11/25/2003** **TD DATE: 11/29/2003**

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP at 7078'.
- 4) RIH with CT and pump 30 sx on top of CIBP at 7078'.
- 5) Pump 20 sx courtesy plug from 2500' to 2250'.
- 6) Pump a 50 sx shoe plug from 627' to surface with CT. Bring cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.