

WORKOVER PROCEDURE

WELL NAME: KY Blue H25-11 **DATE:** 4/6/2016

LOCATION: Qtr/Qtr: NE/SW Section: 25 Township: 3N Range: 65W

Footages: 1980' FSL & 1980' FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-16894

ENGINEER: Benjamin Daniell 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24@ @ 601' KB Elevation: 4828'
Surface Cmt: 185 sx GL Elevation: 4817'
Long St Csg: 3 1/2" 9.5# J-55 @ 5017' TD: 7232'
Long St Cmt: 550 sx PBDT: 4610'
Long St Date: 4/11/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Sussex Perforations 4432' - 4480'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1.9" 2.9# @ 4390' Rods: NA
Pump: NA
Misc.: _____

PRODUCTION STATUS: Producing

COMMENTS: Losing money; doesn't pay for tubing replacment/cleanout/seat nipple/lubricator

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1.9" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 4382', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 750'. Pump 250 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.