

WORKOVER PROCEDURE

WELL NAME: Goetzel 01-29 **DATE:** 3/28/2016
LOCATION:
Qtr/Qtr: SW/NE Section: 29 Township: 6N Range: 66W
Footages: 1980' FNL & 1980' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-11325

ENGINEER: John Hatch 303.505.6589 7 Day Notice Sent: _____
B. Lawrence (Halliburton) 303.513.1199 Do not start operations until: _____
(Please notify Engineer of any major changes prior to work) Notice Expires: _____

OBJECTIVE: Well Abandonment

WELL DATA: Surface Csg: 8-5/8"; 24 ppf; unknown grade set at 432' KB Elevation: 4742'
Surface Cmt: 385 sx GL Elevation: 4727'
Long St Csg: 4-1/2"; 11.6 ppf; M-80 set at 4505.2' TD: 7208'
Long St Csg: 4-1/2"; 10.5 ppf; J-55 set at 7185' PBTD: 7133.5'
Long St Cmt: 275 sx
Long St Date: 11/4/1983

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6882' - 6898'
Perforation Interval (2): Codell Perforations 7074' - 7090'
Tubing: 2-3/8"; 4.7 ppf; J-55 @ 7062.2' Rods: NA
Pump: NA
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6832', dump bail 2 sx of cement on top.
- 4) Perforate at 532'.
- 5) RIH w/ CT. Set a 20 sx cement plug from 2400' to 2200'
- 6) POOH and RD CT. Pump 205 sx shoe plug down production casing. Bring cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.