

WORKOVER PROCEDURE

WELL NAME: ROTHE STATE B36-10 **DATE:** 4/20/2016

LOCATION:

Qtr/Qtr: NW/SE Section: 36 Township: 5N Range: 64W
Footages: 1875 FSL & 1968 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-19215

ENGINEER: Jon Lefor 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8 24# @ 360' KB Elevation: 4604'
Surface Cmt: 250 SX GL Elevation: 4594'
Long St Csg: 3 1/2 7.7# M-75 @ 6822' TD: 6822'
Long St Cmt: 155 SX PBTD: 6720'
Long St Date: 10/21/1996

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6478' - 6490'
Perforation Interval (2): Codell Perforations 6654' - 6668'
Perforation Interval (3): _____
Perforation Interval (4): _____
Tubing: 2 1/16" 3.25# J-55 @ 6627' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6428', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 475'. Pump 200 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.