

WORKOVER PROCEDURE

WELL NAME: HERGENREDER BB32-16D **DATE:** 4/25/2016
LOCATION:
Qtr/Qtr: SE/SE Section: 32 Township: 5N Range: 63W
Footages: 852 FSL & 470 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-21275

ENGINEER: Jon Lefor 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8 24# J-55 @ 630' KB Elevation: 4580
Surface Cmt: 255 SX GL Elevation: 4570
Long St Csg: 4 1/2 11.6# M-80 @ 7428' TD: 7428
Long St Cmt: 270 SX PBTD: 7066
Long St Date: 10/14/2003

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6284' - 6380'
Perforation Interval (2): Codell Perforations 6542' - 6553'
Perforation Interval (3): Dakota Perforations 7224' - 7260'
Perforation Interval (4): _____
Tubing: 2 3/8" 4.7# J-55 @ 6537' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6234', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 750'. Pump 300 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.