

## WORKOVER PROCEDURE

**WELL NAME:** HESTER 31-23 **DATE:** 4/19/2016  
**LOCATION:**  
Qtr/Qtr: SW/NW Section: 31 Township: 7N Range: 66W  
Footages: 1982 FNL & 754 FWL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-25183

**ENGINEER:** JOHN HATCH 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major changes prior to work) Do not start operations until: \_\_\_\_\_  
Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @853' KB Elevation: 4931'  
Surface Cmt: 300 sx GL Elevation: 4915'  
Long St Csg: 4 1/2" 11.60#, M-80 @7593' TD: 7609'  
Long St Cmt: 435 sx PBDT: 7514'  
Long St Date: 10/11/2007

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 7382' - 7401'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" @ 7344' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7332', pump 38 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 953'. Pump 348 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.