

WORKOVER PROCEDURE

WELL NAME: MERCER C11-30D **DATE:** 4/27/2016
LOCATION:
Qtr/Qtr: SW/SW Section: 2 Township: 4N Range: 64W
Footages: 390 FSL & 245 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-30042

ENGINEER: Jon Lefor 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8 32# J-55 @ 608' KB Elevation: 4640'
Surface Cmt: 271 SX GL Elevation: 4624'
Long St Csg: 4 1/2 11.6# N-80 @ 6957' TD: 6965'
Long St Cmt: 550 SX PBTD: 6912'
Long St Date: 1/30/2010

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6524' - 6688'
Perforation Interval (2): Codell Perforations 6800' - 6812'
Perforation Interval (3): _____
Perforation Interval (4): _____
Tubing: 2 3/8" 4.7# J-55 @ 6786' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6474', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 725'. Pump 300 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.