

WORKOVER PROCEDURE

WELL NAME: LOLOFF 03 DATE: 5/5/2016

LOCATION: Qtr/Qtr: NE/NW Section: 35 Township: 5N Range: 64W

Footages: 660' FNL & 2020' FWL

COUNTY: WELD STATE: CO API #: 05-123-11067

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 360' KB Elevation: 4646'
Surface Cmt: 360 sx GL Elevation: 4636'
Long St Csg: 4 1/2" 11.6# @ 6830' TD: 6840'
Long St Cmt: 175 sx + 50 sx PBTD: 6640'
Long St Date: 3/16/1983

Plug Back (Sand or CIBP): Composite Bridge Plug @ 6650 w/ sand up to 6640' (12/13/2004)
Perforation Interval (1): Niobrara Perforations 6478' - 6590'
Perforation Interval (2): Codell Perforations 6754' - 6764'
Perforation Interval (3):
Tubing: 2 3/8" 4.7# J-55 tbg @ 6465' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

- PROCEDURE:
1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 6428', dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
6) POOH w/ workstring to 460'. Pump 150 sx shoe plug. Cement to surface.
7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.