

## WORKOVER PROCEDURE

**WELL NAME:** Cervi USX CC23-02 **DATE:** 5/16/2016  
**LOCATION:**  
Qtr/Qtr: NWNE Section: 23 Township: 4N Range: 63W  
Footages: 660 FNL & 1980 FEL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-26052

**ENGINEER:** AJ Paine 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8", 24#, J-55 @ 483' KB Elevation: 4673'  
Surface Cmt: 247 sx GL Elevation: 4657'  
Long St Csg: 4 1/2", 11.6#, M-80 @ 7438' TD: 7441'  
Long St Cmt: 790 sx PBTD: 7128'  
Long St Date: 11/11/2007

Plug Back (Sand or CIBP): Plug Remnants  
Perforation Interval (1): Niobrara Perforations: 6298' - 6387'  
Perforation Interval (2): Codell Perforations: 6556' - 6566'  
Perforation Interval (3):  
Tubing: 2 3/8", 4.7#, J-55 @ 6522' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: SN & Pump off Bit @ EOT

**PRODUCTION STATUS:** SI since October 2014.  
**COMMENTS:**

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH and laydown 2 3/8" tubing.
- 3) RU WL. RIH to tag CIBP or fill. PBTD @ 7128' in 2011.
- 4) RIH w/ CIBP. Set @ 6248'; dump 2 sx cement on top
- 5) Unland casing. Cut casing off @ 2200'. POOH and laydown 4 1/2" casing.
- 6) RIH w/ workstring to pump 100 sx stub plug where casing was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 583'. Pump 205 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.