

WORKOVER PROCEDURE

WELL NAME: Cervi 11-35 **DATE:** 5/24/2016
LOCATION:
Qtr/Qtr: NWNW Section: 35 Township: 4N Range: 63W
Footages: 664 FNL & 657 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-21032

ENGINEER: AJ Paine 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8", 24# @ 526' KB Elevation: 4762'
Surface Cmt: 370 sx GL Elevation: 4752'
Long St Csg: 4 1/2", 11.6#, LS-75 @ 7287' TD: 7297'
Long St Cmt: 170 sx PBDT: 6908'
Long St Date: 11/7/2002

Plug Back (Sand or CIBP): **Sand**
Perforation Interval (1): Niobrara Perforations: 6448' - 6540'
Perforation Interval (2): Codell Perforations: 6648' - 6658'
Perforation Interval (3): J Sand Perforations: 7108' - 7116'
Tubing: 2 3/8" @ 6909' Rods: _____
Pump: _____
Misc.: SN and notched collar @ EOT

PRODUCTION STATUS: Well is SI. Attempted to bring well BOL at end of 2015. Would need pumping unit to produce.
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH and laydown 2 3/8" tubing.
- 3) RU WL. RIH to tag CIBP or fill. PBDT @ 6908' in 2004 when landing tubing.
- 4) RIH w/ CIBP. Set @ 6398'; dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off @ 2500'. POOH and laydown 4 1/2" casing.
- 6) RIH w/ workstring to pump 100 sx stub plug where casing was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 626'. Pump 220 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.