

<b>Operator:</b>	Francis Energy Inc.		
<b>Well Name:</b>	Eisenach #2		
<b>Legal:</b>	SENE, Section 12, Township 6N, Range 66W		
<b>Location:</b>	Weld, CO		
<b>API:</b>	05-123-12469		
<b>Surface:</b>	8.625" 24# @ 308'	<b>Hole Size:</b> 12.25"	<b>TOC:</b> Surface
<b>Production:</b>	4.5" 11.6# @ 7,290'	<b>Hole Size:</b> 7.875"	<b>TOC:</b> 6,400' (verbal Form 6)
<b>Perforations:</b>	7,200'-7,210' (Codell)		
<b>TD:</b>	7,290'		

## P&A Procedure

1. Conduct pre-job safety meeting and complete daily JSA
2. Dig out to find wellhead and check pressure
3. Cut cap off, extend surface pipe to achieve ground level
4. MIRU WO unit, NU BOP, tally all pipe to be ran in well
5. Mill cement down to 450'
6. TOOH, remove BHA for milling
7. TIH to 1600' based off of pipe talley and pump a 200' plug (1600-1400')
  - a. 90 sx of 15.8# class G neat 1.15 cu./ft. yield cement, (1400' – 1600')
  - b. Wait 4 hours and tag plug
8. TIH to 450' based off of pipe talley and pump a 450' plug to surface (450'-0')
  - a. 200 sx of 15.8# class G neat 1.15 cu./ft. yield cement, (450' – 0')
  - b. Wait 4 hours and tag plug
9. RDMO WO unit
10. Remove extension of surface pipe. Top off if necessary
11. Weld back on cap with ID plate, inscribed with well location, and identity
12. Backfill, clean location
13. P&A complete