

WORKOVER PROCEDURE

WELL NAME: SIDWELL 26-1G4 **DATE:** 2/4/2016
LOCATION:
Qtr/Qtr: NE/NE Section: 26 Township: 6N Range: 64W
Footages: 659' FNL: & 661' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-17833

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 530' KB Elevation: 4646'
Surface Cmt: 295 sx GL Elevation: 4632'
Long St Csg: 3 1/2" 7.7# @ 6995' TD: 7014'
Long St Cmt: 318 sx (calc'd) + 35 sx + 240 sx PBTD: 6883'
Long St Date: 2/15/1994

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 6795' - 6805'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 1/16" 3.25# J-55 tbg @ 6768' Rods: _____
Pump: _____
Misc.: Casing Patch @ 5439' (1/8/2008)

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6745'. RIH w/ workstring to pump 15 sx on top of CIBP @ 6745'.
- 4) POOH w/ workstring to 2500'. Pump 10 sx balance/courtesy plug. POOH w/ workstring.
- 5) Unland casing (if able). Cut casing (in slips if unable to unland) @ 630'. POOH w/ casing laying down on trailer.
- 6) RIH w/ workstring to pump 200 sx stub/shoe plug where csg was pulled. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.