

WORKOVER PROCEDURE

WELL NAME: GILL LAND 22-3 DATE: 8/8/2016

LOCATION: Qtr/Qtr: NW/NW Section: 22 Township: 6N Range: 64W

Footages: 660' FNL & 660' FWL

COUNTY: WELD STATE: CO API #: 05-123-11359

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 210' KB Elevation: 4754'
Surface Cmt: 175 sx GL Elevation: 4744'
Long St Csg: 4 1/2" 11.6# @ 7062' TD: 7062'
Long St Cmt: 175 sx PBTD: 7020'
Long St Date: 10/2/1983

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perforations 6932' - 6945'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 2 3/8" 4.7# ? tbg @ 6898' Rods:
Pump:
Misc.: Casing Patch @ 3340' (2/19/2003)

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RIH w/ workstring and TUBING-SET CIBP. Set CIBP @ 6882'. Pump 30 sx cement on top of CIBP @ 6882'.
4) POOH w/ workstring to 2500'. Pump 15 sx courtesy plug.
5) POOH w/ workstring to 930'. Pump 75 sx shoe plug. Cement to surface.
6) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
7) Cut surface casing off 6'-8' below ground.
8) Clean up location. Reclaim location. RDMO.