

WORKOVER PROCEDURE

WELL NAME: Dinnel C27-29D DATE: 9/8/2016
 LOCATION: Qtr/Qtr: SW/SW Section: 22 Township: 4N Range: 64W
 Footages: 608' FSL: & 672' FWL
 COUNTY: WELD STATE: CO API #: 05-123-31948

ENGINEER: Baxter Whittington 7 Day Notice Sent: _____
 (Please notify Engineer of any major Do not start operations until: _____
 changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 757' KB Elevation: 4690'
 Surface Cmt: 257 sx GL Elevation: 4677'
 Long St Csg: 4 1/2" 11.6# M-80 @ 7079' TD: 7085'
 Long St Cmt: 570 sx PBTD: 7032'
 Long St Date: 11/1/2010

Plug Back (Sand or CIBP): Tbg Tally @ 7032'
 Perforation Interval (1): Nio Perforations 6654' - 6810'
 Perforation Interval (2): Codell Perforations 6920' - 6932'
 Perforation Interval (3): _____
 Tubing: 2-3/8" @ 6788' Rods: NA
 Pump: NA
 Misc.: _____

PRODUCTION STATUS: PR
 COMMENTS: Uneconomic to perform Annular Fill for BH concerns.

PROCEDURE: SEE COA ON APPROVED PROCEDURE

- 1) MIRU Workover rig, pump & tank.
- 2) Unland 2 3/8" tbg. POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6605', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 2500' and pump 20 sk courtesy plug from 2500' - 2245'.
- 5) Unland casing. Cut casing off @ 2100'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug @ 2150' (ETOC= 1850'). If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 870'. Pump 284 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.