

WORKOVER PROCEDURE

WELL NAME: BIERIG 08-26 **DATE:** 10/5/2016
LOCATION:
Qtr/Qtr: SE/NE Section: 26 Township: 5N Range: 66W
Footages: 1950 FNL: & 1341 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-25622

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24.0#, grade? @ 489' KB Elevation: 4763'
Surface Cmt: 345 sx GL Elevation: 4753'
Long St Csg: 4 1/2" 11.60, grade? @ 7351' TD: 7373'
Long St Cmt: 100 sx PBTD: 7314'
Long St Date: 2/18/2005

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6904' - 7044'
Perforation Interval (2): Codell Perforations 7204' - 7216'
Perforation Interval (3): _____
Tubing: No tbq d/h Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Well is currently S/I
COMMENTS: A cast iron flow through plug set @ 7150' - 7152'

PROCEDURE:

- 1) Verify Form 17 bradenhead test has been completed prior to MIRU
- 2) MIRU Workover rig, pump & tank.
- 3) If there is tbq d/h, POOH w/ tbq and lay down, otherwise go to step #4.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 6854', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 589'. Pump 220 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. RDMOL.