

WORKOVER PROCEDURE

WELL NAME: Ocoma G35-23 **DATE:** 10/5/2016

LOCATION: Qtr/Qtr: NE/SE Section: 35 Township: 4N Range: 65W

Footages: 1335 FSL & 1226 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-21980

ENGINEER: Jeanne Van Slambrouck 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 550' KB Elevation: 4811'

Surface Cmt: 225 sx GL Elevation: 4795'

Long St Csg: 4 1/2" 11.6#, M-80 @ 7249' TD: 7280'

Long St Cmt: 280 sx PBTD: 7229'

Long St Date: 11/27/2004

Plug Back (Sand or CIBP): _____

Perforation Interval (1): Niobrara Perforations 6830' - 6970'

Perforation Interval (2): Codell Perforations 7102' - 7114'

Perforation Interval (3): _____

Perforation Interval (4): _____

Tubing: 2 3/8" 4.7# J-55 tbg @ 7086' Rods: _____

Pump: _____

Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: Provide 48 hr notice of plugging MIRU via electronic form 42.

Abandon flowlines as per Rule 1103. File electronic form 42 once abandonment completed.

PROCEDURE:

- 1) Prior to plugging operations, perform a bradenhead test.
- 2) MIRU Workover rig, pump & tank.
- 3) POOH w/ 2 3/8" tbg and lay down.
- 4) RIH w/ workstring w/ tubing-set CIBP. Set CIBP @ 6780', dump bail 2 sx cement on top.
- 5) POOH w/ workstring to 4400' and pump 20 sx balance plug across sussex.
- 6) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 7) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 700'. Pump 270 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.