

WORKOVER PROCEDURE

WELL NAME: RHOADARMER 01-26B **DATE:** 10/5/2016

LOCATION: Qtr/Qtr: SW/NE Section: 26 Township: 5N Range: 66W

Footages: _____ & _____

COUNTY: WELD **STATE:** CO **API #:** 05-123-24888

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24.0#, grade? # 490' KB Elevation: 4753'
Surface Cmt: 250 sx GL Elevation: 4743'
Long St Csg: 4 1/2" 11.60#, grade? @ 7772' TD: 7832'
Long St Cmt: 264 sx PBTD: 7665'
Long St Date: 5/10/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6854' - 7002'
Perforation Interval (2): Codell Perforations 7176' - 7190'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70#, J-55 @ 7142' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Well is currently S/I

COMMENTS: _____

PROCEDURE:

- 1) Verify Form 17 bradenhead test has been completed prior to MIRU
- 2) MIRU Workover rig, pump & tank.
- 3) POOH w/ 2 3/8" tbg and lay down.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 6804', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 590'. Pump 220 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. RDMOL.