

WORKOVER PROCEDURE

WELL NAME: STATE HOPPE 16-01 DATE: 11/1/2016

LOCATION: Qtr/Qtr: SW/SW Section: 16 Township: 6N Range: 66W

Footages: 561 FSL & 664' FWL

COUNTY: WELD STATE: CO API #: 05-123-12232

ENGINEER: JOHN HATCH 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24.0#, grade? @ 352' KB Elevation: 4775'
Surface Cmt: 275 sx GL Elevation: 4764'
Long St Csg: 4 1/2" 11.60#, N-80 @ 7261' TD: 7282'
Long St Cmt: 225 sx PBTD: 7261'
Long St Date: 1/15/1985

Plug Back (Sand or CIBP):
Perforation Interval (1): Niobrara Perforations 6859' - 6994'
Perforation Interval (2): Codell Perforations 7164' - 7178'
Perforation Interval (3):
Tubing: 2 3/8" 4.70#, grade? @ 7038' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 6809', dump bail 2 sx of cement on top.
4) RIH w/ workstring to pump 50 sx stub plug where csg @ 2500'
5) POOH w/ workstring to 452'. Pump 34 sx shoe plug. Cement to surface.
6) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
7) Cut surface casing off 6'-8' below ground.
8) Clean up location. RDMOL.