

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2016

Submitted Date:

11/17/2016

Document Number:

678200509**FIELD INSPECTION FORM**
 Loc ID 317102 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10330Name of Operator: INVESTMENT EQUIPMENT LLCAddress: 412 W PLATTE AVECity: FT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Rebol, Dave		daverebol@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107667	PIT	AC			-	CHM TANK BATTERY PIT	EI
107668	PIT	AC			-	CHM TANK BATTERY PIT	EI

General Comment:

Environmental Inspection. Produced water pit (west) berms adjacent to the roadside have multiple animal burrows that may threaten the pit berm integrity. Improve the pit berms to ensure produced water pit integrity. The berms around the oil skim tank should be improved to ensure adequate containment of potential spills.

Inspected Facilities				
Facility ID: 107667	Type: PIT	API Number: -	Status: AC	Insp. Status: EI
Facility ID: 107668	Type: PIT	API Number: -	Status: AC	Insp. Status: EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Extensive animal burrowing in western pit berms. Eastern pit berms are much more robust than the western berms.

Corrective Action

Maintain pit berms to ensure produced water pit integrity.Date: 12/30/2016c**Fencing:**Fencing Type: Fencing Condition: Comment:

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment:

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment:

Corrective Action

Date: **COGCC Comments**

Comment	User	Date
<u>Erosion from and animal burrows on the western produced water pit berm require improvement/BMP installation.</u>	youngr	11/17/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678200511	Animal burrows at tank battery sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005843
678200512	Animal burrows at treater berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005844
678200513	Inadequate secondary containment berms at oil skim tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005845

678200514	Animal burrows and berm material erosion W side of PW pits	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005846
678200515	Animal burrow in W produced water pit berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005847
678200516	Animal burrows in W produced water pit berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005848
678200517	Animal burrows in W produced water pit berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005849
678200518	View S across E produced water pit berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005850