

WORKOVER PROCEDURE

WELL NAME: WARREN E35-05 **DATE:** 12/6/2016
LOCATION:
Qtr/Qtr: SW/NW Section: 35 Township: 6N Range: 65W
Footages: 1980 FNL & 660 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-16119

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23#, grade? @ 340' KB Elevation: 4675'
Surface Cmt: 300 sx GL Elevation: 4656'
Long St Csg: 2 7/8" 6.50#, N-80 @ 7095' TD: 7126'
Long St Cmt: 200 sx PBTD: 7080'
Long St Date: 9/4/1992

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6663' - 6801'
Perforation Interval (2): Codell Perforations 6951' - 6967'
Perforation Interval (3): _____
Tubing: 1.90" 2.76#, J-55 @ 6928' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Well is currently S/I for regulatory emission compliance
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1.90" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6613', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 590'. Pump 238 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.