

Inspector Name:

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109**FIELD INSPECTION FORM**

Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 8 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
	LUJAN, CARLOS	2A Doc Num:		

Operator Information:

OGCC Operator Number: 10442

Name of Operator: HUNTER RIDGE ENERGY SERVICES LLC

Address: 370 17TH STREET #1700

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Middleton, Brett		Brett.Middleton@encana.com	Environmental Specialist
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW
Rider, Lindsey		Lindsey.Rider@encana.com	Manager, Field Environmental
Kasten, Matt		Matthew.Kasten@encana.com	Environmental
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region

General Comment:

Environmental inspection conducted as a follow-up to Site Assessment and Remediation in the valley north and downgradient of the A27 pipeline spill/release (Spill/Release Point ID #446199, REM #9748). Cool and sunny. On Site with Brett Middleton from Encana/Hunter Ridge (HR) and geologist Wesley Toews from LTE, Rifle office.

The drilling operation was conducted to complete the Phase III Environmental Assessment, document submitted to the COGCC on 10/06/2016 (doc #401125566). A roto sonic drilling rig was used to improve core sampling recovery and well construction. Poorly cemented sandstone was encountered mostly on monitoring wells on both sides (east and west) of the valley. Clayey soil was encountered on monitoring wells in the valley, on the east side of the creek. Today, Oct 20, 2016, the subcontractor is completing MW-18 (See attached photos). Water level at about 53' bgs. No free product observed at this point.

Note: During the process of pouring sand, it was noticed that sand got lost at about 40 feet bgs (more sand had to be poured than expected). Driller indicated that the well had not caved in.

COGCC Comments

Comment	User	Date
The COGCC will continue to inspect the Site as Site Assessment and Remediation activities progress. Encana will continue to submit periodic updates.	lujanc	12/19/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
671000496	Completing MW-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031504
671000497	Pouring sand	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031505
671000498	Measuring water level	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031506



Inspection Date:

10/20/2016

Submitted Date:

12/19/2016

Document Number:

671000495

671000499	Finishing installation of MW-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031507
-----------	---------------------------------	---

--	--	--