

WORKOVER PROCEDURE

WELL NAME: Stroh 35-04 **DATE:** 11/30/2016
LOCATION:
Qtr/Qtr: NW/NW Section: 35 Township: 5N Range: 64W
Footages: 661 FNL & 671 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-17028

ENGINEER: Jon Lefor 7 Day Notice Sent: _____
(Please notify Engineer of any major changes prior to work) Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 20# @ 536' KB Elevation: 4657'
Surface Cmt: 200 sx GL Elevation: 4646'
Long St Csg: 3 1/2" 7.7#, M-75 @ 6925' TD: 6925'
Long St Cmt: 90 sx PBTB: 6852'
Long St Date: 6/29/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6509' - 6665'
Perforation Interval (2): Codell Perforations 6771' - 6782'
Perforation Interval (3): _____
Perforation Interval (4): _____
Tubing: 2 1/16" 3.25# CW-55 tbg @ 6762' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: Provide 48 hr notice of plugging MIRU via electronic form 42.
Abandon flowlines as per Rule 1103. File electronic form 42 once abandonment completed.

PROCEDURE:

- Prior to plugging operations, perform a bradenhead test. If any pressure remains at the conclusion of the test or any
- 1) liquids were present call COGCC engineer for sampling requirements. Submit form 17 within 10 days.
 - 2) MIRU Workover rig, pump & tank.
 - 3) POOH w/ 2 3/8" tbg and lay down.
 - 4) RU WL, RIH w/ CIBP. Set CIBP @ 6459', dump bail 2 sx of cement on top.
 - 5) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. 100' of
- 6) cement is required, at least 50' in casing and at least 50' above csg, to be verified by tagging.
 - 7) POOH w/ workstring to 640'. Pump 175 sx shoe plug. Cement to surface.
- If circulation not maintained to surface then tag plug, must be at 486' or shallower, provide 10 sx plug at surface Leave
- 8) at least 100' of cement in the casing for each plug.
 - 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
 - 10) Cut surface casing off 6'-8' below ground.
 - 11) Clean up location. Reclaim location. RDMO.