

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2017

Submitted Date:

03/15/2017

Document Number:

671000518**FIELD INSPECTION FORM**

Loc ID 324469	Inspector Name: LUJAN, CARLOS	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED																																
2A Doc Num: _____			Findings: 11 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																
Operator Information: OGCC Operator Number: <u>77330</u> Name of Operator: <u>SG INTERESTS I LTD</u> Address: <u>100 WAUGH DR SUITE 400</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77007</u>																																			
Contact Information: <table border="1" style="width:100%"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Guffey, Bud</td> <td></td> <td>bguffey@sginterests.com</td> <td>Superintendent</td> </tr> <tr> <td>Sanford, Eric</td> <td></td> <td>esanford@sginterests.com</td> <td>Operation & Land Manager</td> </tr> <tr> <td>Stranathen, Thane</td> <td></td> <td>tstranat@blm.gov</td> <td>BLM</td> </tr> <tr> <td>Spencer, Stan</td> <td></td> <td>stan.spencer@state.co.us</td> <td>EPS, NW Region</td> </tr> <tr> <td>Lujan, Carlos</td> <td></td> <td>carlos.lujan@state.co.us</td> <td>EPS, NW Region</td> </tr> <tr> <td>Fischer, Alex</td> <td></td> <td>alex.fischer@state.co.us</td> <td>Environmental Supervisor, NW</td> </tr> <tr> <td>Blanchard, Amanda</td> <td></td> <td>ablanchard@sginterests.com</td> <td>SG Interests - Environmental Manager</td> </tr> </tbody> </table>				Contact Name	Phone	Email	Comment	Guffey, Bud		bguffey@sginterests.com	Superintendent	Sanford, Eric		esanford@sginterests.com	Operation & Land Manager	Stranathen, Thane		tstranat@blm.gov	BLM	Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region	Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region	Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW	Blanchard, Amanda		ablanchard@sginterests.com	SG Interests - Environmental Manager
Contact Name	Phone	Email		Comment																															
Guffey, Bud		bguffey@sginterests.com	Superintendent																																
Sanford, Eric		esanford@sginterests.com	Operation & Land Manager																																
Stranathen, Thane		tstranat@blm.gov	BLM																																
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region																																
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region																																
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW																																
Blanchard, Amanda		ablanchard@sginterests.com	SG Interests - Environmental Manager																																
General Comment: Environmental inspection conducted in response to a spill report (spill point ID #449315). Temperature around 36 oF, blue sky and sunny. Met on site with Amanda Blanchard, Eric Sanford, and Bud Guffey from SG, and Thane Stranathan from BLM, Montrose. A produced water tank overflowed. About 200 bbls were released within the secondary containment. s not clear. According to Bud G., SG superintendent, who was onsite in the morning of the discovery, it was hard to determine how much water, if any, seeped through the earthen berm because of snow melt on site. According to his latest estimates one barrel or less may have seeped. The earthen berm looks well constructed and maintained. It is covered with gravel to minimize erosion. No traces of fine sediment was observed that could've resulted from a significant seepage through the earthen berm. Maximum water level mark within the secondary containment was well below the top of the berm. Pad is properly identified with visible sign. Tanks are labeled. A fence protects the tank battery and the secondary containment. Storm water management system includes a diversion storm water ditch on the perimeter of the pad and a bar ditch along the access road. Rock check dams were observed on the road side ditch along the access road to control velocity, retain sediments and control erosion. Minimal (or no) erosion was observed on site or on the access road.																																			

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**Type of Spill: PRODUCED WATEREstimated Spill Volume: 200

Comment: Within secondary containment. Preliminary soil analysis inside the secondary containment, outside of the berm, and on the road side ditch indicate that all parameters analyzed are within Table 910-1

Corrective Action: Submit an Action Plan to evaluate 1) berm conditions (imperviousness) and secondary containment improvement/upgrades as needed; 2) Pipeline system improvements to avoid similar incidents in the future.

Date: 03/31/2017Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
<u>Note: Action Plan and analytical results have already been submitted with supplemental e-form 19 spill report.</u>	lujanc	03/15/2017
<u>A follow-up inspection will be conducted during the summer 2017.</u>	lujanc	03/09/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401234669	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099536
671000519	Photo Report SG Fed 24-1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099397