

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2017

Submitted Date:

11/09/2017

Document Number:

682402965

FIELD INSPECTION FORM

Loc ID 322194 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10454
Name of Operator: PETROSHARE CORPORATION
Address: 9635 MAROON CIRCLE #400
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		fwitsell_premier@comcast.net	
		sami@petrosharecorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209648	WELL	SI	08/01/2017	OW	039-06553	NORDMAN TRUST 41-20	RI

General Comment:

This is a stormwater inspection. This is a short corrective action date because sediment discharge off location was observed.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
Comment: Stained soil was observed at location. Refer to the attached inspection photos for more detail.				
Corrective Action: Remove or remediate stained soil per Rule 906.a.			Date:	12/07/2017

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 209648 Type: WELL API Number: 039-06553 Status: SI Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Fail					

Comment: This location is not in compliance with Reclamation Rule 1002.f.(2). Operator has not implemented stormwater and erosion control BMPs in accordance with good engineering practices to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Sediment discharge from location is evident along the northeast well pad and stormwater run-on onto the western location is causing site degradation.

Corrective Action: Install or repair required BMPs per Rule 1002.f. Operator needs to control and manage sediment discharge from leaving location, repair gully erosion occurring along the northeast well pad and the western cut slope area. Operator needs repair erosion along the access road and install BMPs along the access road.

Date: 11/23/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401454346	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298301
682402966	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298299