

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2017

Submitted Date:

11/09/2017

Document Number:

682402967**FIELD INSPECTION FORM**

Loc ID 322196 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		fwitsell_premier@comcast.net	
		sami@petrosharecorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209653	WELL	PR	12/06/2012	OW	039-06558	RUNNING CREEK 11-21	RI

General Comment:

This is a stormwater inspection at the tank battery location. This is a short corrective action date because sediment discharge off location was observed.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location is not in compliance with Reclamation Rule 1002.f.(2). Operator has not implemented stormwater and erosion control BMPs to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Sediment discharge from location is evident along the northwest and southern location. Refer to the attached inspection photos for more detail.

Corrective Action: Install or repair required BMPs per Rule 1002.f. Operator needs to control and manage sediment discharge from leaving location, repair gully erosion occurring along the northwest and southern location.

Date: 11/23/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
It should be noted the Running Creek well pad to the northeast of the tank battery location appeared to have stormwater erosion issues (gully erosion) as well but COGCC staff did not inspect the location due to time constraints. COGCC would recommend correcting the stormwater erosion issues at the well pad before COGCC staff conducts a future inspection.	binschusc	11/09/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401454347	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298302
682402968	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298300