

Procedure

- 1 Contact landowner and state representative 48 hours prior to commencing work on this well
- 2 Build temporary pad and access road for completion rig and cement unit
- 3 Cut off dry hole marker
- 4 Verify pipe size and weld on wellhead flange and riser
- 5 MIRU completion rig
- 6 MU BHA
- 7 RIH to 375' and drill out existing cement plug
- 8 Continue to RIH to 2500' or as deep as possible without drilling
- 9 Continue to circulate mud to ensure hole clean out
- 10 POOH and LD BHA
- 11 TIH to 2500'
- 12 RU cementers
- 13 Pump 30 sx balanced plug from 2500' - 2400'
- 14 POOH to 482'
- 15 Pump 170 sx balanced plug from 482' - Surface
- 16 POOH and LD tubing
- 17 RDMO completion rig
- 18 Dump 50' cement inside and outside surface casing
- 19 Cut off wellhead and riser to 4' below ground level
- 20 Weld on dry hole marker
- 21 Clean location and reclaim