

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2018

Submitted Date:

03/07/2018

Document Number:

679700820

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10311  
Name of Operator: SRC ENERGY INC  
Address: 1675 BROADWAY SUITE 2600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Inspections, Field		cogccinspections@srcenergy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454029	SPILL OR RELEASE	CL	02/20/2018		-	Lucero 34-10 Flowline	EI
454050	SPILL OR RELEASE	CL			-	Lucero 34-10 flowline 2	EI

**General Comment:**

Empty text area for general comments.

**Inspected Facilities**

Facility ID: 454029 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Facility ID: 454050 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

## Environmental

### Spill/Remediation:

Comment: COGCC Environmental Staff Inspection of Operator's implementation of Remediation Project 11033 for the investigation and remediation of two releases discovered on the Lucero 34-10 flowline. Operator had hauled 1 truck of impacted soil from Spill 2 (Spill ID 454050) and planned to continue excavating until impacts removed. Soil samples will be collected from sidewalls to confirm remaining soil complies with Table 910-1. Operator to backfill excavation, install new poly flowline from wellhead to production equipment, backfill trench and reinstall source area monitoring wells to monitor effectiveness of excavation and groundwater amendments. COGCC also inspected the open flowline trench and trench spoils and did not observe impacts beyond those reported by Operator at spill ID 454029 and 454050.

Corrective Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

### Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401566878	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4396551">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4396551</a>
679700821	Lucero 34-10 inspection photos 03-07-2018	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4396550">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4396550</a>