

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401582336

Date Received:

03/21/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LP
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Leonard, Mike</u>		<u>mike.leonard@state.co.us</u>
<u>Kinder, Morgan</u>		<u>CO2Source_Regulatory@kindermorgan.com</u>
<u>Rabinowitz, Daniel</u>	<u>970-385-1363</u>	<u>drabinow@blm.gov</u>
<u>Telecky, Barbara</u>		<u>btelecky@blm.gov</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685304485
Inspection Date: 03/15/2018 FIR Submit Date: 03/19/2018 FIR Status:

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP Company Number: 46685
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 393066

Location Name: GOODMAN POINT Number: 22-23 PAD County: MONTEZUMA
Qtrqtr: SENE Sec: 32 Twp: 37N Range: 18W Meridian: N
Latitude: 37.423650 Longitude: -108.847660

FACILITY - API Number: 05-083-00 Facility ID: 419734

Facility Name: GOODMAN POINT (GP) Number: 22
Qtrqtr: SENE Sec: 32 Twp: 37N Range: 18W Meridian: N
Latitude: 37.423650 Longitude: -108.847660

CORRECTIVE ACTIONS:

1 CA# 115021

Corrective Action: Comply with Rule 603.f.

Date: 04/21/2018

Response: CA COMPLETED

Date of Completion: 03/21/2018

Operator
Comment:

This corrective action was investigated on 3/20/2018. The "risers" noted in the inspection report are actually grounding rods that were installed for use with directional tools during well drilling activities. Since the location was constructed on sandstone bedrock, a grounding rod for the directional tools used to drill the wells could not be driven into the ground. The site required drilling and blasting in order to be constructed and the blasting contractor drilled vertical shot holes to depths between 40 and 45 feet in order to accommodate installation of the grounding rods. Each grounding rod consisted of two (2) 25-foot joints of 1-inch diameter steel tubing. On 3/21/2018, both joints of tubing were successfully removed from the west side of the location but it was only possible to remove the top joint of tubing from the southeast corner. Both holes were backfilled with native soil and sub-meter latitude/longitude coordinates were recorded for both. Photos of the removal activity are attached to this FIRR.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Hannigan

Signed: _____

Title: EHS Supervisor

Date: 3/21/2018 4:54:42 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401582401	Photo: Removing grounding rod
401582421	Photo: Southeast grounding rod hole
401582422	Photo: West grounding rod hole
401582424	Photo: Southeast grounding rod removed
401582427	Photo: West grounding rod removed

Total Attach: 5 Files