

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401663457
Date Received:
06/05/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Sessions, Tamra

tsessions@logosresourcesllc.com

Rowley, Darren

drowley@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602596

Inspection Date: 04/12/2018

FIR Submit Date: 04/23/2018

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 333510

Location Name: BONDAD 33-10-N33N10W Number: 2SENE County: LA PLATA

Qtrqtr: SENE Sec: 2 Twp: 33N Range: 10W Meridian: N

Latitude: 37.135740 Longitude: -107.897630

FACILITY - API Number: 05-067- -00 Facility ID: 216492

Facility Name: BONDAD 33-10 Number: 16A

Qtrqtr: SENE Sec: 2 Twp: 33N Range: 10W Meridian: N

Latitude: 37.135740 Longitude: -107.897630

CORRECTIVE ACTIONS:

1 ☒ CA# 115997

Corrective Action: Revegetate the western portion of the project area.

Date: 05/31/2018

Response: CA COMPLETED

Date of Completion: 05/30/2018

Operator Comment: A contractor working for BP and LOGOS Operating LLC re-seeded and mulched the western edge of the project area, removed sediment from the drainage around the locations and installed some catch basins and gabion rock to control sediment migration. Erosional channels and rilling along the access road were stabilized. Storm water controls along access were cleaned to de-energize flows and capture sediment.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 115998

Corrective Action: Well pad stormwater diversion needs maintenance, and run-on needs to be controlled and cut-slopes better stabilized. Erosional channels and rilling along the access road needs to be stabilized. Stormwater controls along access need maintenance/repair and improvement to de-energize flows and capture sediment.

Date: 05/31/2018

Response: CA COMPLETED

Date of Completion: 05/30/2018

Operator Comment: A contractor working for BP and LOGOS Operating LLC re-seeded and mulched the western edge of the project area, removed sediment from the drainage around the locations and installed some catch basins and gabion rock to control sediment migration. Erosional channels and rilling along the access road were stabilized. Storm water controls along access were cleaned to de-energize flows and capture sediment.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed: _____

Title: Regulatory Technician

Date: 6/5/2018 1:09:37 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401663457	FIR RESOLUTION SUBMITTED
401663467	Photo
401663468	Photo
401663470	Photo
401663471	Photo
401663473	Photo
401663475	Photo

Total Attach: 7 Files