

# Inspection Photos

Operator: BP Production

API: 05-067-05139

Date: 10/05/2018



**Photo 1. View of the project area from the southwestern corner facing center.**





**Photo 2. View of the western project area from the northwestern corner facing southward. Berms are not stabilized and diversion is full of sediment.**





**Photo 3. View of the area in the southwestern corner of the project area where it appears that stormwater and sediment flows onto the project area toward the western diversion.**





**Photo 4. Another view of the western project area from the southwestern corner facing northward, downstream from Photo 3.**





**Photo 5. View of area in the northwestern project area where diverted stormwater flows toward a culvert leading off of the project area. Sediment is not being properly managed. Culvert is half full of sediment.**





**Photo 6. View of the southern project area from the southwestern corner facing eastward. Berms are not properly stabilized.**





**Photo 7. View of musk thistles (*Carduus nutans*) within the northern interim reclamation area.**





**Photo 8. View of the eastern project area from the northeastern edge facing southward. It appears well pad was cleared and soil/ rocks bermed along the edge.**





**Photo 9. View of cobble run-down in the southeastern project area.**