



SRC ENERGY

**Operator:** SRC Energy  
**Well Name:** Bunn I 35-14  
**Legal:** SESW, Section 35, Township 6N, Range 66W  
**Location:** Weld County, CO  
**API:** 05-123-23285  
**Surface:** 8.625" 24# @ 445' **Hole Size:** 12.25" **TOC:** Surface  
**Production:** 4.5" 11.6# @ 7,293' **Hole Size:** 7.875" **TOC:** 2,732' (CBL)  
**Perforations:** 7,132' – 7,150' (Codell)  
**TD:** 7,300'

P&A Procedure

1. Conduct pre-job safety meeting and complete daily JSA
2. Blow down well if necessary, circulate hole with treated water
3. Dig out around wellhead and perform bradenhead test
4. MIRU WO unit, ND wellhead, NU BOP, tally all pipe
5. TIH w/ 4-1/2" 11.6# CIBP, set at 7,057'
6. Pressure test casing to 500 psi for 15 minutes
7. Set 32 sx on top of CIBP (cover 213' above Niobrara top)
8. TIH w/ 4-1/2" 11.6# CIBP, set at 4,290' (75' above Sussex top)
9. Set 2 sx on top of CIBP
10. TIH to 2,500' and perforate casing
11. TIH w/ 4-1/2" 11.6# CICR, set at 2,400'
  - a. Squeeze perfs w/ 70 sx (300' annulus plug & 100' casing plug)
  - b. Release off of CICR and set 8 sx on top (100' plug)
12. Cut 4.5" casing at 860' and POOH
13. TIH to 910' and pump stub plug (0' – 910')
  - a. 262 sx of 15.8# class G neat 1.15 cu./ft. yield cement
  - b. 465' out of surface casing
  - c. Wait 4 hours and tag plug
14. RDMO WO unit
15. Dig up wellhead and cut off 10' below restored ground level, top off if necessary
16. Weld on cap with ID plate, inscribed with well location, and identity
17. Backfill, clean location
18. P&A complete