

Inspection Photos

2/04/2019

Operator: MALLARD EXPLORATION LLC # 10670

Location ID: 453517

Inspection Doc. Number: 682504483

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the southeast corner of the location, facing west. Photo shows perimeter stormwater ditch. Photo also show disturbed areas along perimeter of location appears to have been seeded and mulched.



Photo 2: Photo taken from the southeast corner of the location, facing west. Photo shows perimeter stormwater ditch, and sediment pond/trap. Photo also show disturbed areas along perimeter of location appear to have been seeded and mulched.



Photo 3: Photo taken from the southeast end of the location. Photo shows the outlet of the sediment pond/trap has been armored. Outlet protection appears to be sufficient and in proper functioning condition.



Photo 4: Photo taken from the northeast corner of the location. Photo shows the perimeter stormwater ditch has been installed. Ditch appears to have been installed in accordance with good engineering practices and in proper functioning condition. Photo also shows disturbed areas along perimeter of location appears to have been seeded and mulched.



Photo 5: Photo taken from the northeast corner of the location. See comments under photo 4.



Photo 6: Photo taken from the northwest corner of the pad, facing south. See comments under photo 4.



Photo 7: Photo taken from the northwest corner of the pad, facing east. See comments under photo 4.



Photo 8: Photo taken from the northwest corner of the location, facing south. See comments under photo 4. Photo also shows topsoil stockpile appears to have been stabilized and seeded.



Photo 9: Photo taken from the southwest corner of the pad, facing north. See comments under photo 4. Photo also shows topsoil stockpile appears to have been stabilized and seeded.



Photo 10: Photo taken from the southwest corner of the pad, facing east. See comments under photo 4.



Photo 11: Photo taken from the south end of the pad. Photo shows wattles do not appear to have been installed in accordance with good engineering practice. Wattles are required to be trenched in order to be in proper functioning condition.



Photo 12: Photo taken from the south end of the pad. Photo shows wattles do not appear to have been installed in accordance with good engineering practice. Wattles are required to be tightly “butted” at the ends.



Photo 13: Photo taken from the south end of the location. Photo shows culvert and rock armoring. Photo also shows tracking pad.