

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401994451

Date Received:

04/03/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Singer, Sheila		ssinger@hpres.com
Storey, Mike		mstorey@hpres.com
Barber, Matt		mbarber@hpres.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404598
Inspection Date: 02/28/2019 FIR Submit Date: 03/11/2019 FIR Status:

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 417093

Location Name: Fox Creek Number: 33 NWNW County:
Qtrqr: NWN Sec: 33 Twp: 12N Range: 63W Meridian: 6
W
Latitude: 40.972070 Longitude: -104.443292

FACILITY - API Number: 05-123-00 Facility ID: 417093

Facility Name: Fox Creek Number: 33 NWNW
Qtrqr: NWN Sec: 33 Twp: 12N Range: 63W Meridian: 6
W
Latitude: 40.972070 Longitude: -104.443292

CORRECTIVE ACTIIONS:

1 CA# 123098

Corrective Action:

Date: 04/08/2019

Comply with Rule 1002.f. to properly install BMPs in accordance with good engineering practices. In addition, perform one of the two following corrective actions:

- 1) Provide construction calculations from the site specific stormwater plan demonstrating that a stabilized outlet structure is not required, or
- 2) Install a stabilized outlet structure(s) in accordance with good engineering practices per Rule 1002.f.

Response: CA COMPLETED

Date of Completion: 04/03/2019

Operator Comment: Following control measures have been implemented - tracking on stockpiles, filtrex staked at the bottom of fill slopes not equipped with a ditch, ditches installed on some perimeter locations and around stockpiles, tracking on stockpiles, sediment traps installed at SW and SE corners of facility to catch drainage from ditch around spoils and topsoil stockpile. We further note the following: COGCC photo #6 indicates that ditch has not been constructed to adequate depth - however, there is no ditch CM present in the area shown in the picture.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rusty Frishmuth

Signed: _____

Title: EHS Director

Date: 4/3/2019 10:51:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401994576	Photo #2
401994602	Photo #2
401994611	Photo #1

Total Attach: 3 Files