

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/15/2019

Submitted Date:

04/26/2019

Document Number:

695100514

FIELD INSPECTION FORM
 Loc ID 307400 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10084

Name of Operator: PIONEER NATURAL RESOURCES USA INC

Address: 5205 N O'CONNOR BLVD STE 200

City: IRVING State: TX Zip: 75039

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217615	WELL	PR	05/29/1997	GW	071-06394	PCW 23-16	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment:

PHOTO 7: DEBRIS STUCK ON ELECTRICAL COMPONENTS ON LOCATION APP. 10' UPGRADE FROM WELLHEAD.
 PHOTO 10: MORE DEBRIS SHOWING PATH STORMWATER FOLLOWED DURING EVENT.

Corrective Action:

Comply with Rule 603.f .

Date: 05/15/2019

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities				
Facility ID: 217615	Type: WELL	API Number: 071-06394	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: PHOTO 3: THERE IS AN EROSION CHANNEL OBSERVED BY STORMWATER ENTERING LOCATION FROM A BREACH IN BMP TO THE SOUTH OF LOCATION
 PHOTO 4: TRENCH ACROSS LOCATION APP. 40' BY 3' AT ITS WIDEST POINT.
 PHOTO 5: APP. 40' BY 3' STRIP OF GRAVEL SEDIMENT OBSERVED MIGRATING OF LOCATION.
 PHOTO 6: CLOSER VIEW OF GRAVEL DEPOSITED OF LOCATION BY STORMWATER.
 PHOTO 8: THERE IS A BMP FAILURE ON UPGRADE SIDE OF LOCATION.
 PHOTO 9: PHOTO TAKEN FROM STANDING IN BREACH IN BMP.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 05/15/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402023759	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808387
695100554	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808378