

Location

Lease Road:			
Type	Access		
comment:	PHOTO 3: NO DITCHING OR BERMING ON ROW TO PREVENT STORMWATER POOLING ON ROW AND ROW SURFACE MATERIAL FROM MIGRATING OFF OF ROW AND BEYOND ORIGINAL ROW DISTURBANCE AREA. PHOTO 4: CLOSER VIEW FROM PREVIOUS PHOTO (PHOTO 3). PHOTO SHOWING STORMWATER POOLING ON ROW AND EROSION OF ROW SURFACE MATERIAL OFF OF ROW. PHOTO 5: CLOSER VIEW OF ROW EROSION AND ROW SURFACE MATERIAL MIGRATION OF ORIGINAL ROW DISTURBANCE AREA FROM THE PREVIOUS 2 PHOTOS (PHOTO'S 3 & 4). SEE STORMWATER SECTION OF THIS INSPECTION FOR MORE CORRECTIVE ACTION DETAILS.		
Corrective Action:	INSTALL OR REPAIR BMP'S TO PREVENT STORMWATER POOLING ON ROW AND TO PREVENT ROW SURFACE MATERIAL FROM MIGRATING OFF OF ROW IN ACCORDANCE WITH RULE 1002.f.	Date:	09/12/2019

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1	Comment: PLUMBED TO SURFACE	
Corrective Action:			Date: <input style="width: 20%;" type="text"/>
Type: Ancillary equipment	# 1	Comment: TELEMETRY EQUIPMEPNT	
Corrective Action:			Date: <input style="width: 20%;" type="text"/>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width: 20%;" type="text"/>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <input style="width: 20%;" type="text"/>

Inspected Facilities

Facility ID: 264594 Type: WELL API Number: 071-07712 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Fail			

Comment: PHOTO 6: ANOTHER AREA APP. 200 YARDS SOUTH FROM PREVIOUS PHOTOS OF NO DITCHING OR BERMING ON ROW TO PREVENT STORMWATER CAUSING ROW SURFACE MATERIAL TO MIGRATING OFF OF ROW AND BEYOND ORIGINAL ROW DISTURBANCE AREA. PHOTO 7: CLOSER VIEW OF EROSION FROM THE PREVIOUS PHOTO (PHOTO 6).
 PHOTO 8: VIEW OF SAME EROSION FROM PREVIOUS 2 PHOTOS (PHOTO'S 6 &7). FROM THE OPOSITE SIDE (SOUTH VIEW).
 PHOTO 9: NATURAL DRAIN UPSLOPE FROM ROW EROSION AREA WITH NO BMP'S IN PLACE.

Corrective Action: **INSTALL OR REPAIR BMP'S TO PREVENT STORMWATER POOLING ON ROW AND TO PREVENT ROW SURFACE MATERIAL FROM MIGRATING OFF OF ROW IN ACCORDANCE WITH RULE 1002.f.**

Date: 09/12/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402107533	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4877613
695101012	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4877593