

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2019

Submitted Date:

08/14/2019

Document Number:

690200048**FIELD INSPECTION FORM**
 Loc ID 335492 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Gardner, Mike		mgardner@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
466515	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI

General Comment:

On August 8, 2019 COGCC Environmental Staff (John Heil) conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Spill ID 466515.

Operator reported a leaking produced water line riser on the east edge of the GM 343-32 pad (Doc #402136269).

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 4.6

Comment: The pipeline was excavated prior to inspection date. The pipeline was visible inside an open fenced excavation and TEP staff was repairing the pipeline. The excavation measured approximately 30 feet by 20 feet wide by 10 feet deep (See photos). COGCC staff did not observe any staining within the excavation or experience any hydrocarbon odors. There was no stockpiled soil observed on the location at time of inspection. The excavation is located on the north side of the access road and to the west of a stormwater drainage. The fluids entered a culvert on the south side of the road, exited on the north side of the road and flowed approximately 40 feet north into an off-site stormwater retention basin. COGCC staff observed orange and dark brown stained soil within the drainage and the stained soils had a slight hydrocarbon odor (See photos).

Corrective Action: The operator shall submit a supplemental spill report within ten days of discovery of the release with all of the additional information required by Rule 906.b.1.

Date: 08/16/2019

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690200055	20190808 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909147