

### **Summary of Re-entry and Re-plugging Operations: TRUEBLOOD SKEETERS 1-13**

1. Survey and locate plugged wellbore. Set a stake and record as-drilled GPS coordinates.
2. Excavate around wellbore to expose the top of the surface casing.
3. Cut existing cap off wellbore. Weld a slip collar to 8-5/8" casing and necessary length of casing to reach ground level. Weld another 8-5/8" slip collar.
4. Install wellhead and BOP.
5. Drill out surface cement plug with 6-1/2" bit. Pressure test surface casing to 250 psi before drilling out surface casing plug. Drill out surface casing plug.
6. Continue drilling or RIH to 1600'. Spot OH plug from 1600'-1500' with Class G cement (30 sks).
7. POOH and spot plug from 497' to surface with class G cement (175 sks).
8. Cut off casing 5' below surface and weld on a cap to seal the well.
9. Cover up the well and remediate the disturbed area.