




00209472

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
 DEPARTMENT OF NATURAL RESOURCES
 SUBMIT ORIGINAL AND 1 COPY



FOR OFFICE USE			
ET	FE	UC	SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen of plug back to a different reservoir.
 Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL GAS WELL COALBED METHANE INJECTION WELL OTHER

5. FEDERAL/INDIAN OR STATE LEASE NO.
N/A

6. PERMIT NO.
88-1165

2. NAME OF OPERATOR
HS RESOURCES, Inc.

RECEIVED
JAN 03 1995

7. API NO.
05-123-14146

3. ADDRESS OF OPERATOR
3939 Carson Avenue

8. WELL NAME
Castor

CITY STATE ZIP CODE
Evans CO 80620

9. WELL NUMBER
2

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 14 below.)

10. FIELD OR WILDCAT
Gemini

At surface
1980' FSL & 1980' FWL

At proposed production zone
Same

12. COUNTY
Weld

11. QTR. QTR. SEC., T.R. AND MERIDIAN
**NE SW Sec. 12-T7N-R59W
 6th PM**

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- PLUG AND ABANDON
- MULTIPLE COMPLETION
- COMMINGLE ZONES
- FRACTURE TREAT
- REPAIR WELL
- OTHER:

13B. SUBSEQUENT REPORT OF:

- FINAL PLUG AND ABANDONMENT
 SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG
- ABANDONED LOCATION (WELL NEVER DRILLED - SITE MUST BE RESTORED WITHIN 6 MONTHS)
- REPAIRED WELL
- OTHER:
 *Use Form 5 - Well Completion or Recompletion Report and Log for subsequent report of Multiple/Commingled Completions and Recompletions

13C. NOTIFICATION OF:

- SHUT-IN/TEMPORARILY ABANDONES DATE:
 (REQUIRED EVERY 6 MONTHS)
- PRODUCTION RESUMED DATE:
- LOCATION CHANGE (SUBMIT NEW PLAT)
- WELL NAME CHANGE
- OTHER:

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent)

15. DATE OF WORK **02-01-94**
1. Set CIBP @ +/- 6500' (27' above top of perforations) and dump bail 2 sx cmnt on top of plug.
 2. Cut off 4-1/2" casing @ 5700'. (50' above cement top)
 3. Lay down 4 1/2" casing
 4. PU 2 3/8" tubing and pump 30 sx cement plug with base of plug @ +/- 5730'.
 5. Pump 30 sx cement plug with base @ 265' (1/2 in and 1/2 out of btm of 8 5/8" csg)
 6. Pump 10 sx cement plug from 30' to surface
 7. Cut surface casing off 4' below ground level and weld plate on top

16. I hereby certify that the foregoing is true and correct

SIGNED *Larry Webb* PHONE NO. **303-330-0614**

NAME (PRINT) **Larry Webb** TITLE **Area Manager** DATE **12-29-94**

(This space for Federal or State office use)

APPROVED *DK Deacon* **DKD**
 CONDITIONS OF APPROVAL, IF ANY:

SR. PETROLEUM ENGINEER
 TITLE **O & G Cons. Comm.** DATE **JAN 20 1995**