

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402287071

Date Received:
01/15/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Max Knop

303-825-4822

mknop@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697600752

Inspection Date: 01/14/2020

FIR Submit Date: 01/14/2020

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 317790

Location Name: NESSU-62N66W Number: 17SESE County: _____

Qtrqr: NENE Sec: 20 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.129894 Longitude: -104.794911

FACILITY - API Number: 05-123- -00 Facility ID: 453316

Facility Name: Nessu 1,2,3,4,12,14,15,16 battery Number: _____

Qtrqr: NENE Sec: 20 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.129894 Longitude: -104.794911

CORRECTIVE ACTIONS:

1 CA# 135957

Corrective Action: investigate spill and determine approximate quantity and general cause of spill/release within 72 hours and report those findings to COGCC. Complainant reported first noticing spill area a a problme when working the field in spring of 2019. Provide rough sketch of flowlines in area related to Nesssu wells and Nesssu tank battery as shown on attached 2019 aerial image.

Date: 01/17/2020

Response: CA COMPLETED

Date of Completion: 01/15/2020

Approximate location of Nesssu flowlines attached.

Based on visual observation of surface contamination, KPK estimates approximately 29 gallons were released.

Operator Comment: Estimate based on flowline depth of 48" and 25% soil porosity. Surface has been heavily disturbed due to farming activities. Most likely cause of release due to failure of 3" fiberglass flowline.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Knop

Signed: _____

Title: Gen Mangr of Air Quality

Date: 1/15/2020 4:43:02 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---------------------------|
|-------------------------------|---------------------------|

| | |
|-----------|-------------------------------|
| 402287077 | Flowline Map - Nesssu Battery |
|-----------|-------------------------------|

Total Attach: 1 Files