

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2020

Submitted Date:

02/14/2020

Document Number:

689901797

FIELD INSPECTION FORM

Loc ID 333857 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1801 BROADWAY SUITE 350

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262957	WELL	PR	03/04/2003	GW	071-07593	UINTAH 21-27	RI
276220	WELL	PR	02/22/2005	GW	071-08311	UINTAH 21-27 TR	RI

General Comment:

This is a location and stormwater inspection.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type		
Comment:		
Corrective Action:		Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion issues along the main access road. Stormwater from the road is causing erosion along the side of the road. Stormwater directed from culvert outlets has caused erosion to occur. Areas of erosion need to be repaired, stabilized, and reclaimed. BMP's must be implemented in accordance with good engineering practice and must be maintained.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 03/14/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID:	Lat:	Long:
-----------------------------	------------------	---------	------	-------

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____
 Corrective _____

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____
 Corrective _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____
 Corrective _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Comment: The water in the pit is nearing 2 ft. of freeboard and may need to be lowered soon.
 Corrective _____

Date: _____

COGCC Comments

Comment	User	Date
Due to snow cover, other erosion issues may have not been noticed and not all nearby locations were inspected.	CostaR	02/14/2020
Upon reviewing historic aerial imagery, it appears the Crazy Woman 32-27 location may be contributing to erosion down the hill near the road shown in photo 4.	CostaR	02/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402314177	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5068942
689901798	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5068938