

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402318941

Date Received:

02/21/2020

Spill report taken by:

Hughes, Jim

Spill/Release Point ID:

471621

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: KINDER MORGAN CO2 CO LP Operator No: 46685
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002
Contact Person: Michael Hannigan
Phone Numbers: Phone: (970) 882-5532 Mobile: (970) 403-9501 Email: michael_hannigan@kindermorgan.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402313001

Initial Report Date: 02/13/2020 Date of Discovery: 02/13/2020 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWNW SEC 13 TWP 37N RNG 18W MERIDIAN N

Latitude: 37.470397 Longitude: -108.790697

Municipality (if within municipal boundaries): County: MONTEZUMA

Reference Location:

Facility Type: GAS COMPRESSOR STATION [X] Facility/Location ID No 436392

Spill/Release Point Name: Yellow Jacket Produced Water Pump [] No Existing Facility or Location ID No.

Number: 103B [] Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: 111 bbls Produced Water

Land Use:

Current Land Use: OTHER Other(Specify): Industrial (Compressor Plant)

Weather Condition: 40 Deg F, clear, wind 5 mph

Surface Owner: FEE Other(Specify):

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State [] Residence/Occupied Structure [] Livestock [] Public Byway [] Surface Water Supply Area []

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

The spill resulted from the failure of the packing on produced water pump 103B located inside a concrete containment area just south of the tank farm. Produced water from the release initially stayed inside the concrete containment area and was directed to the sump however the sump pump failed to activate. The produced water filled the sump, backed up into the containment area and then overflowed onto the ground surface on the north side of the containment area. The volume of the spill is based on our SCADA tank fluid level trend which was calculated to be a total of 111 barrels released and 72 barrels recovered and pumped back into the tank.

List Agencies and Other Parties Notified:

Was there a Grade 1 Gas Leak associated with this E & P waste spill or release? Yes No

If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with this E & P waste spill or release? Yes No

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

SPILL/RELEASE DETAIL REPORTS

#1 Supplemental Report Date: 02/16/2020

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	111	72	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) Soil Groundwater Surface Water Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 29 Width of Impact (feet): 12

Depth of Impact (feet BGS): 2 Depth of Impact (inches BGS): 0

How was extent determined?

Direct measurement of saturated soil areas adjacent to the containments.

Soil/Geology Description:

Soil type is silty, sandy gravel. The concrete pump pedestal and containment area was constructed by placing a layer of clean gravel on compacted native soil. The native soil is silty clay.

Depth to Groundwater (feet BGS) 900 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest Water Well _____ None Surface Water 700 None

Wetlands _____ None Springs _____ None

Livestock 600 None Occupied Building 1500 None

Additional Spill Details Not Provided Above:

As described in the initial report, produced water from the release was initially captured by the concrete containment area and directed to a collection sump. However, the sump pump failed to activate and the produced water eventually filled the sump and backed up through drain pipes into three (3) separate containment areas. Those containment areas were all constructed at approximately the same elevation such that the produced water backed up and overflowed onto the ground surface on the north sides of each of the three containment areas. The release areas are located adjacent to the produced water pump that failed, the glycol pump containment area approximately 150 feet west and the blowdown tank containment area approximately 50 feet northwest of the glycol pumps. Mike Pasquin, Montezuma County Emergency Manager, was contacted via email regarding the release.

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: Corrective Actions Completed (documentation attached)

Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Michael Hannigan

Title: EHS Supervisor Date: 02/21/2020 Email: michael_hannigan@kindermorgan.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

402319124	AERIAL PHOTOGRAPH
-----------	-------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)