

Inspection Photos

API: 055-06155

Operator: PETROGLYPH OPERATING

Inspection Date: 2/27/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020

Inspection Photos



Photo 1. Facing southwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020

Inspection Photos



Photo 2. There is vehicle rutting along the road. The ruts will cause stormwater to flow down along the ruts and could cause erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020

Inspection Photos



Photo 3. The side of the road has no BMP's installed to prevent erosion. The long downward grade of the road will accelerate stormwater and may deepen the side shown by red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020

Inspection Photos



Photo 4. Vehicle use of the road during wet conditions is causing ruts and damage along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020

Inspection Photos



Photo 5. Vehicle use of the road during wet conditions is causing ruts and damage along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020

Inspection Photos



Photo 6. Facing northwest along the access road. The long downward grade of the road could accelerate stormwater along the side of the road and also along the vehicle ruts.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020

Inspection Photos



Photo 7. Facing northwest along the road at the water bar. It appears sediment is accumulating at outlet (red arrow). This may cause stormwater to flow over the water bar and down the road. A sediment trap or other BMP may be needed at the end of the water bar outlet.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020

Inspection Photos



Photo 8. Facing northwest along the access road. Vegetation appears to be establishing along the side of the road. Vehicle rutting is not occurring in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020

Inspection Photos



Photo 9. Facing south toward the location. The vegetation appears to be well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020

Inspection Photos



Photo 10. Facing east toward the location. The vegetation appears to be well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 2/27/2020