

Inspection Photos  
Operator: Catamount Energy  
API#: 067-08193  
Date: 6/1/2020



Photo 1. View of the northern fill slope from the northeastern corner facing westward. Revegetation is progressing, largely with grasses such as smooth brome, western wheatgrass, and intermediate wheatgrass.





Photo 2. View of erosional channeling occurring downstream from cobble BMP in the northern project area. Wattle is failed. Cobbles are not sufficient to stabilize stormwater flows in this area.





Photo 3. View of erosional channeling in Photo 2, facing downstream. Erosional channel is approximately 2 feet wide and 1 foot deep.





Photo 4. View of sediment deposition and cobble that is washed off of the project area. Reclamation and remediation is needed in these areas.





Photo 5/6. View of dense Canada thistles and Russian thistle debris within the northern project area.





Photo 7. View of reference area comprised of open grass field with grasses such as smooth brome and western wheatgrass.