

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2020

Submitted Date:

06/17/2020

Document Number:

689501071

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Oakman, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1675 BROADWAY, STE 2800
 City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476918	SPILL OR RELEASE	AC	06/16/2020		-	Robert G Berge #2	EI

General Comment:

This is an environmental inspection of Spill ID 476918 reported by Operator on 6/15/2020. There were no environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Any corrective actions from previous inspections that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 476918 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: _____

Comment: At the time of inspection the excavation had been partially backfilled and a soil wall was constructed on the eastern side of the excavation to mitigate the spread of contaminants into the flowing irrigation ditch (photos 2&4). Excavation crew were on site and were awaiting additional equipment/gear to continue spill clean-up. Booms had been deployed at two locations in the irrigation ditch; a sheen was noted in the irrigation canal at the booms (photos 4-6). A piece of removed flowline was sitting outside of the excavation; corrosion was visible on a portion of the pipe (photo 3).

Corrective Action: Per Rule 906.b., the Operator shall submit a supplemental Form 19 not more than 10 calendar days after the spill/release is discovered (6/25/2020). On the supplemental Form 19 operator is to provide the root cause of the incident and preventative measures that will be taken to prevent reoccurrence. Please give the location of the failure (i.e. 6 O'clock position) and if the root cause is corrosion explain if it is external or internal. Operator will provide confirmation soil sample analytical data that verifies compliance with Table 910-1. Operator shall also collect surface water samples from the irrigation ditch (upstream, downstream, and at location of spill). Include sample location diagram summary table of analytical results compared to table 910-1 standards and lab report via supplemental Form 19 no later than 45 days from the Spill Report Date (7/30/2020).

Date: 06/25/2020

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402424649	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5177766
689501072	Field Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5177753