

Summary of Re-entry and Re-plugging Operations (Federal 1 05-123-05519)

1. Survey and locate plugged wellbore. Set a stake and record as-drilled GPS coordinates.
2. Excavate around wellbore to expose the top of the surface casing.
3. Cut existing cap off wellbore. Weld a slip collar to 8-5/8" casing and necessary length of casing to reach ground level. Weld another 8-5/8" slip collar.
4. Install wellhead and BOP.
5. Drill out existing cement plugs with 6-1/2" bit. Pressure test surface casing to 250 psi before drilling out surface casing plug. Continue drilling or RIH to 6502'.
6. Spot cement plug from 6502'-5942' with class G cement (206 sks). Tag plug once set.
7. POOH spot cement plug from 4690'-4590' with class G cement (40 sks).
8. POOH spot cement plug from 3950'-3850' with class G cement (40 sks).
9. POOH spot cement plug from 1700'-1600' with class G cement (40 sks).
10. Spot plug from 505' to surface with class G cement (223 sks).
11. Cut off casing 5' below surface and weld on a cap to seal the well.
12. Cover up the well and remediate the disturbed area.